


7-5-85
12.3.8 v.3



ASH GROVE CEMENT WEST, INC.

Inter-Office Memorandum

Date July 5, 1985

To Erik Voldbaek

From Ken Rone

Copies to _____

Subject Activity Report
Week Ending 6/30/85

- * 1. Began haul of University of Washington fly ash to disposal site. ^{U.O.F.W. will pay \$6.25 cost.} ~~to be 100 tons/day truck.~~ Rate appears
- * 2. Sent nine wage roll employees and two supervisors to Durkee for plant tour. Mr. Cooke and his staff went out of their way to accommodate and the trip generated the expected enthusiasm.
3. Met with Jim Repman, Pioneer Construction Materials. They would like to use our unloading system, personnel and property to gain better advantage on large fill projects in the Seattle market. They offered to pay 50¢/ton for services rendered including loading into their trucks. See Mr. Dash.
- (4) Met with Mr. Dash and Mr. Post regarding consolidation of the 12 merchantable and two unmerchantable types of cement we presently inventory. Decision was made to classify Class G as unmerchantable, to consider Genstar Type I as Seattle Type I and to consolidate all Type II and ~~Type III~~ designations into single Type II and ~~Type III~~ categories. This results in seven merchantable types and 5,100 tons designated for regrinding.
5. Decisions required on status of White River and Blum properties. The location of our work is no longer confidential, and we have yet to negotiate any rights to the material. I recommend that the Blum site be purchased from Allied Corp. and that an exclusive mining agreement on White River be negotiated with Weyerhaeuser within 10 days.
- * 6. Conducted audiometric monitoring on all plant employees.
7. Complaint by Genstar Structures on low strength. Jim Post will follow-up. All plant data within normal limits.
- (8) Type III cement manufactured in Durkee is unacceptable at Concrete Technology Corp., due to high water demand. They were switched back to Type III manufactured in Seattle.
9. No accidents. Visitors: Ed Miller, Everett Curzon.

KJR:imb

USEPA SF



1261141

AGC2E000111